



Fitting Instructions for 3M™ Half Facepiece Respirators

Issue Date 06/01/00


Wearing your elastomeric half facepiece respirator



1 Place the respirator over your nose and mouth with bottom straps unfastened.




2 Pull the top strap over your head, placing the head cradle on the crown of your head.




3 Hook the bottom straps together behind your neck.



4 Adjust strap tension to achieve a secure fit.





Check the seal of your elastomeric half facepiece respirator each time you don the respirator.




1. Positive Pressure User Seal Check

Place the palm of your hand over the exhalation valve cover and *exhale* gently. The facepiece should bulge slightly. If air leaks between the face and the face seal of the respirator, reposition it and adjust the straps for a more secure seal. If you cannot achieve a proper seal, **do not** enter the contaminated area. See your supervisor.




2. Negative Pressure User Seal Check

Place your thumbs over the center of the filters and *inhale* gently. The respirator should collapse slightly. If air leaks between the face and the face seal of the respirator, reposition it and adjust the straps for a more secure seal. If you cannot achieve a proper seal, **do not** enter the contaminated area. See your supervisor.



Place the palms of your hands over the cartridges and *inhale* gently. The facepiece should collapse slightly. If air leaks between the face and the face seal of the respirator, reposition it and adjust the straps for a more secure seal. If you cannot achieve a proper seal, **do not** enter the contaminated area. See your supervisor.

 <p>⚠ WARNING:</p>	<ul style="list-style-type: none">• Breathing certain dusts, mists, fumes, gases or vapors can cause sickness or death.• This respirator can help protect you when worn during all times of exposure.• If you cannot achieve a proper fit, do not enter the contaminated area. See your supervisor.• See your supervisor with questions regarding which respirator to wear and its proper use, or call 3M: 1-800-243-4630 Internet: www.3M.com/occsafety E-mail: occsafety@mmm.com (In Canada, call 3M: 1-800-267-4414, E-mail: ohes@ca.mmm.com).• OSHA standard 1910.134 and the CSA standard Z94.4-93 requires that the wearer be fit tested.• Do not use with beards or other facial hair or other conditions that prevent a good seal between the face and the face seal of the respirator.
--	--

Technical Assistance U.S.
1-800-243-4630

Sales Assistance U.S.
1-800-896-4223

Fax On Demand U.S. and Canada
1-800-646-1655

Fax On Demand Outside U.S. and Canada
651-732-0131

Internet
www.3M.com/occsafety

E-mail
occsafety@mmm.com

For other 3M products
1-888-3M HELPS

In Canada, contact:
3M Canada Company, OH&ESD
P.O. Box 5757
London, Ontario N6A 4T1
1-800-267-4414
or 1-800-265-1840, ext. 6137

Internet
www.3M.com/intl/CA/ohes.html

3M Canada E-mail
ohes@ca.mmm.com

Technical Assistance In Mexico
01-800-712-0646

Technical Assistance In Brazil
0800-550705



General Offices
3M Center
St. Paul, MN 55144-1000