



CAUTION: PROTECT BALLS AND RACES FROM SAWDUST, DIRT, PAINT, ETC. SHOULD BEARING BECOME "ROUGH" FROM DIRTY RACES, FLUSH THOROUGHLY WITH HOT SOAPY WATER, RINSE, OVEN DRY AND RE-OIL.



SECTION "A-A"



PART STAMPED WITH TRIANGLE NAME STAMP

3	BALLS6	BALL	1
2	1068	RACE-PLAIN	1
1	1067	RACE-LOCKING	1
DET	PART NUMBER	DESCRIPTION	AMT
C TRIANGLE MANUFACTURING CO.		OSHKOSH, WI.	
NAME		6" L.S.B.	

FIT		////	
PLATING		ELECTRO-GALV	
MATERIAL		SEE DET	
ALL DIMS		±.020 UNLESS SPECIFIED	
USED IN	DATE	PART NO.	
	4-14-76		
DRAWN	SP	6C	
CHECKED	MJK		
SCALE	1 / 1		

CHANGE LEVEL
F 101-05-94